

Citroen Berlingo
EES-753



Citroen Berlingo
EES-753




Citroen Berlingo
EES 753




Citroen Berlingo
EES-753





The image shows a close-up of a metal part, possibly a vehicle chassis or engine component, that is severely corroded. The surface is covered in thick, brown and orange rust, with several holes and deep grooves visible. A bolt is visible in the upper right. The background is dark and out of focus, showing some mechanical parts. In the bottom right corner, there is handwritten text in blue ink.


Citroen Berlingo
EES-753

A photograph showing the underside of a vehicle, specifically the chassis and suspension components. The metal parts are heavily rusted and corroded. A large, cylindrical, corrugated metal component, likely a shock absorber or a large hose, is visible in the center. The background shows a workshop environment with a green floor and a white wall.

Citroën Berlingo
EES-753

Citroen Beilings
EE5-453





citroen Beeking
EES-753


Sitawen Berdango
ZES 453




Citroen Beelding
EES 753



Catzen Borkling
EES-453



Citroen Bozings
EE-453



Citroen Berlingo
EES-753




Citroen Berlingo
EES-753



Citroen Berlingo
EES-753



Citroen Berlingo
EE5-453




Citroen Berlingo
EBS553



Citroen Boling
EE5-753



Citizen Boatings
EES 753



Citroen Berlingo
EES-753



A close-up photograph of the rear side of a Citroën Berlingo. The image shows a black plastic body panel, a silver alloy wheel with a multi-spoke design, and a black tire with 'WINTER' embossed on the sidewall. A red body panel is visible at the top left. The car is parked on a wet, grey concrete surface. Handwritten text in blue ink is located in the lower-left area of the image.

Citroën Berlingo
EES753



UAB AUTOARLITA

Kodas 145590738, PVM mokėtojo kodas LT455907314
K. Donelaičio g. 70, Šiauliai

Šiaulių sporto centras Dubysa

Įm. kodas 145914542
Gumbinės g. 18A, Šiauliai

DEFEKTAVIMO AKTAS

2025 03 27

Šiauliai

2025 03 27 į autoservisą UAB Autoarlita buvo pristatytas automobilis Citroen Berlingo
v/n EES 753, VIN VF7MFWJYB65584044.

Apžiūros metu buvo nustatyti šie gedimai:

1.	Kėbulo korozijos defektai
2.	Važiuklės elementų korozijos defektai
3.	Kuro sistemos nesandarumas
4.	Variklio skysčių prasisunkimas
5.	Išmetimo sistemos nesandarumas
6.	Pašalinis garsas iš variklio skyriaus
7.	Stabdžių sistemos defektai

Įvertinus būtinų defektų kokybišką pašalinimo kainą, ji ženkliai viršija dabartinę automobilio rinkos kainą. Rinkoje automobilis kainuoja nuo 500 Eur, o remontas gali siekti iki 3000 Eur.

Todėl siūlome Jums tai įvertinti ir apsvarstyti galimybę dėl naujesnio automobilio įsigijimo, kadangi automobilis yra nesaugus naudojimui.

Autoserviso vadovas



Arvydas Andriulis

LIETUVOS RESPUBLIKA

LT

Valstybės įmonė „Regitra“

REGISTRACIJOS LIUDIJIMAS

Свидетельство за регистрация / Permiso de circulación / Osvedčeni o registraci /
 Registreringsattest / Zulassungsbescheinigung / Registreerimistunnistus /
 Άδεια κυκλοφορίας/Πιστοποιητικό Εγγραφής / Registration certificate /
 Certificat d'immatriculation / Teastas Cláraithe / Carta di circolazione /
 Registrācijas apliecība / Forgalmi engedély / Certifikat ta' Registrazzjoni /
 Kentekenbewijs / Dowód Rejestracyjny / Certificado de matrícula /
 Certificat de înmatriculare / Osvedčenie o evidencii / Prometno dovoljenje /
 Rekisteröintitodistus / Registreringsbeviset

EUROPOS BENDRIJA

D 005923

A EES753 R MELYNA
 D.1 CITROEN D.3 BERLINGO
 E VF7MFWJYB65584044

(C.1.4) 145914542

C.1.1 ŠIAULIŲ MIESTO SAVIVALDYBĖS
 BIUDŽETINĖ ĮSTAIGA SPORTO MOKYKLIA
 "DUBYSĄ"

C.1.2 --

C.1.3 ŠIAULIAI, GUMBINĖS G. 18A

C.4.1 asmuo yra transporto priemonės
 savininkas

H -- (parašas)
 I 2010-12-21



B 2001-02-23 (B.1) 2008-10-23
 D.2 -- / -- / --
 F.1 1840 kg (F.4) --
 G 1200 kg
 J M1 (J.1) M1-AC---
 K --
 P.1 1868 cm³ P.2 51 kW
 P.3 DYZELINAS
 P.4 NENUSTATYTAS
 Q --
 S.1 5 S.2 --

D 005923